

GENERAL MANAGER REPORT

MAY/JUNE 2026

FIELD OPERATIONS & MAINTENANCE:

- The monthly water sample results came back empty of contamination.
- Well Site vegetation clean-up & removal challenges + disposal
- Dog Tags being placed on Fire Hydrants during the annual water main flushing maintenance
- Inventory on small parts and tools with labels currently being placed on larger district assets (mobile equipments, large hand tools, etc)
- Wellsite electrical issues (misc circuits between wells 1 & 2). Manual operating of well pump for starting and stopping.
- Wellsite electrical issues were resolved and well No.1 electrical panel completion
- Water Leak: Via Pariso between Blackfoot + Manzanita. Repaired by Kelley's Construction
- Generator filters replaced with fluid to be replenished in the upcoming weeks. Generator is expected to be placed back in service in July.

Staff Comments: _____

ADMINISTRATIVE OFFICE SUMMARY

- State Regulator required updating of the district's Bacteriological Site Sample Plan, Asbestos Monitoring Plan, PFAS water sampling requirement to stay in compliance
- Financial Reports, Budget, Rates & Charges, and Forms being updated by staff
- Lead & Copper Water Sample Mailer -Public Notification-
- Monthly Drought Reporting are being completed and filed Online through the SAFER System Portal
- The annual Water Quality Report (CCR) to be completed by the June 30th deadline (DRAFT version sent to our water regulator for review and approval prior to printing and posting)

Staff Comments: _____

MISC TOPICS

- Office and Field Work Load

Staff Comments: ***Dog tags and labels were ordered via Amazon. Completion of the master inventory with labels and dog tags for each fire hydrant expected to be completed by the end of July 2026.***

GENERAL MANAGER REPORT

